BID TABULATION		ITB # / Description:	ITB 7266, Fire Ex	tinguisher/Alarm/S	Bid Opening Date:	5/11/2009
City of Indianapolis		Department:	City Wide Contract		Reviewed By:	David Condon
Purchasing Division		Department Contact:			:	
1 dicilasing Division		Buyer:	Dave Condon (317) 327-4976			:
			Davo comacii (c			
	Vendor	Fairchild Communications	Koorsen Fire	SimplexGrinnell	B&B Construction	1
	Invalid/Valid Bid	Valid	Valid	Valid	Invalid (No Quote Form)	
	Brochure	N/A	N/A	N/A	N/A	
	Insurance	NO	YES	NO	NO	
	Affidavit Non-Collusion	YES	YES	YES	YES	
	Participation Plan / Waiver	YES	YES	YES	YES	
	Exceptions	YES	NO	YES	YES	
		Fairchild Communications	i			
Estimate	d	Annual	Hydro	Recharge	New and/or	
Quantity		Inspection	Test		Replacement	1
	9 ABC 2.5	\$1.93	\$9.30	\$9.30		
18	8 ABC 5	\$1.93	\$13.95	\$16.00	\$45.55	
16	8 ABC 10	\$1.93	\$17.95	\$26.00	\$73.00	1
14	6 ABC 20	\$1.93	\$25.95			
	2 ABC 30	\$2.20	\$41.00	 		
	3 Hood	\$96.80	\$41.00			
	0 2 ½ Pres Foam	\$1.93	\$12.50			
	8 Spill-x 30	\$2.20	\$50.95		\$850.00	
enumenterior su sumenimo en extremente e e e e e e e e e e e e e e e e e e	8 Medal-x 30	\$2.20	\$50.95		\$572.00	
	% +/- Manufacturer's List Price	0%				
THE CONTROL OF THE CO	Alarm Per Hour	\$80.00				
	Sprinkler Per Hour	\$77.00			CONTRACTOR OF THE ABOVE	

in.

•

188 A 168 A 146 A 42 A 23 H 150 2 8 S	ABC 2.5 ABC 5 ABC 10 ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30 Medal-x 30	Koorsen Annual Inspection \$2.00 \$2.00 \$2.00 \$2.00 \$2.00 \$2.00 \$95.00 \$2.00 \$2.00 \$2.00	Hydro Test \$11.10 \$11.10 \$14.00 \$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$17.00 \$22.00 \$30.00 \$80.00 \$875.00 \$92.00 \$365.00	\$43.00 \$67.00 \$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
Quantity 1809 A 188 A 168 A 146 A 23 H 150 2	ABC 5 ABC 10 ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00 \$2.00 \$2.00 \$2.00 \$2.00 \$95.00 \$2.00 \$2.00	Test \$11.10 \$11.10 \$14.00 \$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$12.00 \$17.00 \$22.00 \$30.00 \$80.00 \$875.00 \$92.00 \$365.00	Replacement \$32.00 \$43.00 \$67.00 \$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
1809 A 188 A 168 A 146 A 42 A 23 H 150 2 8 S	ABC 5 ABC 10 ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00 \$2.00 \$2.00 \$2.00 \$95.00 \$2.00 \$2.00	\$11.10 \$11.10 \$14.00 \$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$17.00 \$22.00 \$30.00 \$80.00 \$875.00 \$92.00 \$365.00	\$32.00 \$43.00 \$67.00 \$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
188 A 168 A 146 A 42 A 23 H 150 2 8 S	ABC 5 ABC 10 ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00 \$2.00 \$2.00 \$95.00 \$2.00 \$2.00	\$11.10 \$14.00 \$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$17.00 \$22.00 \$30.00 \$80.00 \$875.00 \$92.00 \$365.00	\$43.00 \$67.00 \$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
168 A 146 A 42 A 23 H 150 2 8 S	ABC 10 ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00 \$2.00 \$95.00 \$2.00	\$14.00 \$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$22.00 \$30.00 \$80.00 \$875.00 \$92.00 \$365.00	\$67.00 \$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
146 A 42 A 23 H 150 2 8 S	ABC 20 ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00 \$95.00 \$2.00 \$2.00	\$15.00 \$15.00 \$425.00 \$15.00 \$20.00	\$30.00 \$80.00 \$875.00 \$92.00 \$365.00	\$110.00 \$495.00 \$2,250.00 \$195.00 \$895.00
42 A 23 H 150 2 8 S	ABC 30 Hood 2 ½ Pres Foam Spill-x 30	\$2.00 \$95.00 \$2.00 \$2.00	\$15.00 \$425.00 \$15.00 \$20.00	\$80.00 \$875.00 \$92.00 \$365.00	\$495.00 \$2,250.00 \$195.00 \$895.00
23 F 150 2 8 S	Hood 2 ½ Pres Foam Spill-x 30	\$95.00 \$2.00 \$2.00	\$425.00 \$15.00 \$20.00	\$875.00 \$92.00 \$365.00	\$2,250.00 \$195.00 \$895.00
150 2 8 S	2 ½ Pres Foam Spill-x 30	\$2.00 \$2.00	\$15.00 \$20.00	\$92.00 \$365.00	\$195.00 \$895.00
8 8	Spill-x 30	\$2.00	\$20.00	\$365.00	\$895.00
					φ5∠5.00
0/	% +/- Manufacturer's List Price	0%			
	Alarm Per Hour	\$70.00			
	Sprinkler Per Hour	\$70.00			
	W. V.				
		SimplexGrinnell			
Estimated		Annual	Hydro	Recharge	New and/or
Quantity		Inspection	Test		Replacement
1809 A	ABC 2.5	\$3.00	\$15.00	\$12.50	\$33.00
188 A	ABC 5	\$3.00	\$15.00	\$17.00	\$44.94
168 A	ABC 10	\$3.00	\$15.00	\$22.50	\$67.92
146 A	ABC 20	\$3.00	\$15.00	\$30.50	\$111.84
42 A	ABC 30	\$3.00	\$15.00	\$75.00	\$509.00
23 F	Hood	\$90.00	\$475.00	\$950.00	\$2,300.00
150 2	2 ½ Pres Foam	\$3.00	\$15.00	\$96.00	\$205.00
8 S	Spill-x 30	\$3.00	\$20.00	\$380.00	\$923.96
8 N	Medal-x 30	\$3.00	\$20.00	\$195.00	\$550.00

•

Alarm Per Hour	\$120.80	
Sprinkler Per Hour	\$76.00	

		B&B Constructio	n		
Estimated		Annual	Hydro	Recharge	New and/or
Quantity		Inspection	Test		Replacement
1809	ABC 2.5	\$1.93	\$9.35	\$9.35	\$31.90
188	ABC 5	\$1.93	\$15.02	\$17.05	\$49.00
168	ABC 10	\$1.93	\$19.42	\$28.05	\$78.65
146	ABC 20	\$1.93	\$28.22	\$44.55	\$150.26
42	ABC 30	\$2.20	\$44.72	\$61.05	\$369.60
23	Hood	\$96.80	\$44.72	\$170.50	N/A
150	2 ½ Pres Foam	\$1.93	\$13.20	\$62.70	\$170.50
8	Spill-x 30	\$2.20	\$55.72	\$250.80	\$818.40
8	Medal-x 30	\$2.20	\$55.72	\$145.20	\$619.30
	% +/- Manufacturer's List Price	0%			
	Alarm Per Hour	\$60.00			i
1	Sprinkler Per Hour	\$60.00			·